PERMIT # _____

CITY OF ST. HELENA NAPA COUNTY, CALIFORNIA TREE PERMIT/CONTRACT APPLICATION FOR CITY TREES

TO: DEPARTMENT OF PUBLIC WORKS
1480 MAIN STREET
ST. HELENA, CA 94574

APPLICANT: PG&E (JOCELYN POWELL)
(Property Owner or Contractor)

JOB LOCATION: 1107 MAIN ST ST. HELENA, CA 94574
(Address, City, State & Zip)

PHONE: (925) 244-3758

EMAIL: J6PC@PGE.COM

I (or we) herby request permission to carry out the following Tree work as required in Section 17.8 & 17.10 of the City of St. Helena Municipal Code:

TREE TRIMMING____ TREE ROOT PRUNING____ TREE REMOVAL X TREE REPLACEMENT ____

DESCRIPTION OF TRIMMING, ROOT PRUNING, REMOVAL AND/OR REPLACEMENT TREES:
Raywood Ash corner of Main St & Pope St.

Estimated Start Date 8/01/16 Estimated Completion Date 08/30/16

DIAGRAM OF LOCATION OF PROPOSED WORK

Attach diagram on separate sheet(s) if necessary

Applicant agrees to comply with all ordinances, regulations, specifications and conditions which may apply or be required as a condition of this Permit/Contract.

Applicant shall indemnify, defend and hold harmless The City of St. Helena and its agents, officers, officials employees and volunteers in interest from and against all claims, damages, losses and expenses including attorney fees arising out of or in connection with work performed under this Permit/Contract, except where caused by the sole negligence or willful misconduct of The City of St. Helena. This obligation of Applicant to indemnify, defend and hold harmless shall continue in effect after the completion of the project authorized under this Permit/Contract.

APPLICANT SIGNATURE: Jocelyn Sh Powell DATE: 6/17/16

PROPERTY OWNER SIGNATURE: _____ DATE: _____

CITY ARBORIST REPORT

Type of Tree(s) RAYWOOD ASH Diameter(s) 16.5" DBH
(Site Sketch Required for Multiple Trees)

Sidewalk Damage: Yes ✓ No _____ Lift in Inches: 4"

Other Damage: SIDEWALK BUCKLED, CURB CRACKED AND LIFTED, STREET BUCKLED

Condition of Location: Good _____ Fair ✓ Poor _____

Hazards Present: Yes ✓ No _____ If Yes, Explain: BUCKLED STREET CAUSES GUTTER WATER TO POOL AT CROSSWALK

Distance of Utilities from Tree: Water N/A Sewer N/A Other _____

Overhead Obstructions: Yes _____ No ✓ If Yes, Explain type and height: _____

Recommend Approval: Yes ✓ No ____

Comments: THIS TREE HAS INNER BRANCH DIE BACK DISEASE, AND WILL NEED TO BE REMOVED IN THE FUTURE

Signature _____ Date _____

City Arborist _____ 6/27/16

* * * * * * * * * * * * * *

SITE SKETCH FOR TREE OR TREES

Attach diagram on separate sheet(s) if necessary